

CHANGES IN PARTS BULLETINS

1052 (Issue 1)	1080 (Issue 1)	1090 (Issue 2)
1064 (Issue 1)	1082 (Issue 2)	1108 (Issue 1)
1067 (Issue 2)	1088 (Issue 2)	1117 (Issue 2)

On the perforators, reperforators, perforator transmitters and reperforator transmitters referred to in the above bulletins, the 122-577 feed roll (straight feed hole) has been replaced by a 110682 feed roll (straight feed hole).

The 122-359 feed roll (advance feed hole) has been replaced by a 110683 feed roll (advance feed hole).

The new feed rolls are designed to eliminate the use of the 81598 bushing.

110682 is equivalent to 122-577 plus 81598

110683 is equivalent to 122-359 plus 81598