

03 August 1991

Re: ST-8000A Assembly Procedures

A5W12 PA960-80012 REV: A (08/01/91)

A6A PA905-08004 REV: B, pages 10 & 11 (08/01/91)

Errors have been discovered in these two production assembly procedures.

1. Replace A5W12 procedure PA960-80012 dated 08/01/91 with the attached procedure.
2. Replace only pages 10 & 11 of A6A procedure 905-08004 dated 08/01/91 with attached new pages (dated 08/03/91).

G. W. Henry
Configuration Manager