Garden City

BELL SYSTEM PRACTICES
TELETYPEWRITER STATIONS

SECTION P90.015
ISSUE: 5 DEC. 1956
AT&TCO STANDARD



FRONT VIEW OF TABLE FOR EMERGENCY TTY



PLAN VIEW OF TABLE FOR REGULAR AND EMERGENCY TTY



LEFT END VIEW OF TABLE FOR REGULAR TTY



FRONT VIEW OF TABLE FOR REGULAR TTY

NOTES:
1. TABLE SHELF SHALL BE CUT AS REQUIRED TO PASS RECTIFIER CORDS BETWEEN SHELF AND REAR PANEL OF TABLE.

15 TTY-15 N TABLE
PRIVATE LINE SERVICE
WITH 128B2 TTY SUB SET

BELL TELEPHONE LABORATORIES, INC.
PRINTED IN U. S. A.
COPYRIGHT, 1957, BY AMERICAN TELEPHONE AND TELEGRAPH COMPANY