

INDEXING DISC ADJUSTMENT

APPARATUS AFFECTED: 35B and 35D Typing Units.

OBJECT: To increase operating margin of the form feed mechanism.

CHANGE: The slack requirement for the indexing disc requirement given in Section 574-220-700, Issue 3, page 72, paragraph 2.69, is changed from "with slack taken up in idler and form start gears to make gap maximum" to, "with slack taken up in idler and form start gears to make gap *minimum*."

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

APPLICATION TO APPARATUS IN THE FIELD: Should be incorporated in all apparatus.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall have the new requirement applied.