

CHANGES AND ADDITIONS
BULLETIN NO. 1090 (ISSUE 2)
PARTS - PERFORATOR TRANSMITTER (MODEL 15)

THE INFORMATION CONTAINED IN THIS CORRECTION SHEET APPLIES TO
PERFORATOR TRANSMITTERS USED FOR SHIPBOARD OPERATION ONLY

Page 1

The 74572 cable-keyboard (W.D.-1986) has been replaced by a 104936 cable-keyboard (W.D.-2143).

Page 14

The cover (assembly) - black wrinkle, illustrated on this page, has been replaced by a new cover (assembly) - black wrinkle. This new cover has a 97911 knob, 34432 washer and an 80516 cotter pin added on each side, which are used to secure the cover to a metal table.

Page 15

The 99873 perforator and counter unit cover (assembly) - black wrinkle has been replaced by a 105022 perforator and counter unit cover (assembly) - black wrinkle. The latter employs a 105023 perforator and counter unit cover in place of the 99875 perforator and counter unit cover, and differs in that it has a large cutout in the front for viewing the indicator on the counter unit. A glass window is used in this cutout which may be ordered as 104868 glass and is secured by means of a 105024 felt, four 104867 clamps, four 2191 lock washers and four 3598 nuts.

Page 16

The 101435 tape reel container (assembly) - black wrinkle has been replaced by a 110734 tape reel container (assembly) - black wrinkle. The latter employs a 104027 tape reel container in place of the 91217 tape reel container and differs in that a 107495 clamp plate and an 1104 thumb screw are used at the top edge for clamping the tape reel cover in position.

Page 17

The 91743 set of spring cushion keytops (communication with "H" stop) has been replaced by a 103652 set of spring cushion keytops (communication with "H" stop) and differs only in that a 99564 keytop (PØ) is used in place of 78961 keytop (PO).