

CHANGES AND ADDITIONS
TO BULLETIN NO. 1109 (ISSUE 1)
PARTS - TRANSMITTER DISTRIBUTOR

PAGE 1

The 73180 toggle switch (assem.) has been replaced by a more durable 107393 toggle switch (assem.) which includes a 91683 nut (hex.) and a 91684 nut (ring).

PAGE 2

The 2084 roller, 1196 screw and 3598 nut, used on the 77049 operating lever, have been replaced by a 112577 roller, 1041 screw and 3606 nut respectively. The 2191 lock washer is to be used with both the new and old style parts, and the 8330 washer is used only with the old style parts. The complete group of new style parts must be used together as they are not individually interchangeable.

PAGE 3

In addition to the 8896 shims (.004" thick), 96874 shims (.002" thick) may be ordered for use between the bracket and the yoke of the universal release magnet, in order to obtain a uniform clearance between the yoke and the armature.

The 4703 spring, used in the 77001 stop arm, has been replaced by an 80581 spring.

PAGE 4

In the 9520 terminal block (assem.), the 300-178 spring anchors have been replaced by 101713 terminals.

In the 77080 slip connection strip (assem.) the 1262 screws (5/16" long) have been replaced by 101456 screws (9/32" long).

PAGE 6

In the top view of the top plate, a 103-27 washer should be listed under the 1162 screw.

The 122-97 bushing - bakelite (.125" long), shown in the lower right corner, has been replaced by 105220 bushing - bakelite (.148" long).

PAGE 7

The 1159 screw (3/8" long), shown in the bottom view of the top plate has been replaced by an 1177 screw (11/32" long).

PAGE 8

The 78206 resistance unit (assem.), having two 78205 resistors of 300 ohms each, has been replaced by a 70361 resistor unit (assem.), having two 70722 resistors of 500 ohms each.